













d_0	$\varnothing 10\text{mm}$

	$h_{nom}=85\text{mm} \mid t_{fix2}=0...10\text{mm}$	
HUS3-C 10	t_{fix1}	$t_{fix1}+t_{fix2}$
10x90	5 mm	5...15 mm
10x100	15 mm	15...25 mm

h_{nom}	h_1
75	85
85	95

h_{nom}	$h_{1.nc}$	$h_{1.nc}$
75	115	85
85	125	95













d_0	$\varnothing 10\text{mm}$

	$h_{nom1}=55\text{mm}$	$h_{nom2}=75\text{mm}$	$h_{nom3}=85\text{mm}$
HUS3-C 10	t_{fix1}	t_{fix2}	t_{fix3}
10x70	15 mm	-	-
10x90	35 mm	15 mm	-
10x100	45 mm	25 mm	15 mm

h_{nom}	h_1
55	65
75	85
85	95








h_{nom}	$h_{1.nc}$	$h_{1.nc}$
55	95	65
75	115	85
85	125	95











d_0	$\varnothing 10\text{mm}$	$\varnothing 8\text{mm}$

$h_{nom2}=75\text{mm}$	
HUS3-C 10	t_{fix2}
10x70	-
10x90	15 mm
10x100	25 mm



d_0	$\varnothing 10\text{mm}$

$\text{min. } t_{fix}=5\text{mm}$	
HUS3-C 10	t_{fix}
10x70	5 mm
10x90	5 mm
10x100	15 mm



	SIW 22-A 1/2" (01)	SIW 6AT-A22 1/2" (01)	SIW 22T-A 1/2" (01)	SIW 22T-A 3/4" (01)	SIW 9-A22 3/4" (01)
HUS3-C 10	✓	✓	✓	✓	✗